

REVISED DRAFT

**SAMPLING AND ANALYSIS PLAN
PART II – QUALITY ASSURANCE
PROJECT PLAN
POST REMOVAL SAMPLING**

**Bonneville Dam Project
Cascade Locks, Oregon**

January 2003

Prepared for:



**U.S. Army Corps of Engineers
Portland District
333 SW First Avenue
Portland, Oregon 97208-2946**

Prepared by:



111 S.W. Columbia, Suite 900
Portland, Oregon 97201-5814
25692710

TABLE OF CONTENTS

List of Abbreviations	iv
Section 1 Project Description.....	1-1
Section 2 Project Organization and Responsibilities.....	2-1
Section 3 Data Quality Objectives.....	3-1
3.1 Background	3-1
3.2 QA Objectives for Chemical Data Measurement.....	3-1
3.2.1 Precision.....	3-2
3.2.2 Accuracy.....	3-2
3.2.3 Representativeness.....	3-2
3.2.4 Comparability.....	3-3
3.2.5 Completeness	3-3
3.2.6 Sensitivity.....	3-3
Section 4 Sampling Locations and Procedures.....	4-1
Section 5 Sample Custody and Holding Times.....	5-1
Section 6 Analytical Procedures	6-1
6.1 Laboratory Procedures	6-1
6.1.1 Semivolatile Organic Compounds (SVOCs)	6-1
6.1.1.1 Sample Preparation.....	6-1
6.1.1.2 Analytical Method.....	6-1
6.1.2 Polychlorinated Biphenyls (PCBs) - Aroclors	6-1
6.1.2.1 Sample Preparation.....	6-1
6.1.2.2 Analytical Method.....	6-1
6.1.3 Organochlorine Pesticides (Pesticides).....	6-2
6.1.3.1 Sample Preparation.....	6-2
6.1.3.2 Analytical Method.....	6-2
6.1.4 Diesel and Heavy Oil Range Organics.....	6-2
6.1.4.1 Sample Preparation.....	6-2
6.1.4.2 Analytical Method.....	6-2
6.1.5 Butyltins	6-2
6.1.5.1 Sample Preparation.....	6-2
6.1.5.2 Analytical Method.....	6-3
6.1.6 Total Metals (except mercury)	6-3
6.1.6.1 Sample Preparation.....	6-3
6.1.6.2 Analytical Method.....	6-3
6.1.7 Mercury.....	6-3
6.1.7.1 Sample Preparation.....	6-3
6.1.7.2 Analytical Method.....	6-3
6.1.8 Total Organic Carbon (TOC).....	6-3
6.1.8.1 Sample Preparation.....	6-3
6.1.8.2 Analytical Method.....	6-4
6.1.9 Grain Size.....	6-4
6.1.9.1 Sample Preparation.....	6-4

TABLE OF CONTENTS

	6.1.9.2 Analytical Method.....	6-4
	6.1.10 pH.....	6-4
	6.1.11 Moisture Content.....	6-4
	6.1.12 Acid Volatile Sulfides (AVS) and Simultaneously Extracted Metals (SEM).....	6-4
	6.1.12.1 Sample Preparation.....	6-4
	6.1.12.2 Analytical Method.....	6-4
	6.1.13 Total Suspended Solids (TSS).....	6-5
	6.1.14 Dissolved Organic Carbon (DOC).....	6-5
	6.1.15 Hardness.....	6-5
Section 7	Calibration Procedures and Frequency.....	7-1
	7.1 Analytical Support Areas.....	7-1
	7.2 Laboratory Instruments.....	7-2
	7.3 Field Instruments.....	7-2
Section 8	Internal Quality Control Checks.....	8-1
	8.1 Batch QC.....	8-1
	8.2 Matrix-Specific QC.....	8-1
	8.3 Additional QC.....	8-2
Section 9	Calculation of Data Quality Indicators.....	9-1
	9.1 Precision.....	9-1
	9.2 Accuracy.....	9-1
	9.3 Completeness.....	9-2
	9.4 Method Detection Limits (MDLs).....	9-2
Section 10	Corrective Actions.....	10-1
	10.1 Incoming Samples.....	10-1
	10.2 Sample Holding Times.....	10-1
	10.3 Instrument Calibration.....	10-1
	10.4 Reporting Limits.....	10-1
	10.5 Method QC.....	10-2
	10.6 Calculation Errors.....	10-2
Section 11	Data Reduction, Review, Validation, and Reporting.....	11-1
	11.1 Data Reduction.....	11-1
	11.2 Data Review.....	11-1
	11.3 Data Validation.....	11-2
	11.4 Data Reporting.....	11-2
	11.5 Laboratory Turnaround Time.....	11-2
Section 12	Preventative Maintenance.....	12-1
Section 13	Performance and System Audits.....	13-1
	13.1 Performance and External Audits.....	13-1
	13.2 Systems/Internal Audits.....	13-1

TABLE OF CONTENTS

Section 14	QC Reports to Management.....	14-1
Section 15	References.....	15-1

TABLES

Table 3-1	QA Objectives Summary
Table 5-1	Sample Methods and Container, Preservation, and Holding Time Requirements for Sediment Samples
Table 5-2	Sample Methods and Container, Preservation, and Holding Time Requirements for Water Samples
Table 6-1	Analytical Methods
Table 6-2	Sediment Reporting Limits
Table 6-3	Water Reporting Limits

APPENDICES

Appendix A	Laboratory USACE Certifications
------------	---------------------------------